

**ENGINEERING
MANUFACTURING
PROCESSES**

D. MASLOV, V. DANILEVSKY and V. SASOV

**ENGINEERING MANUFACTURING
PROCESSES
IN MACHINE
AND ASSEMBLY SHOPS**

Translated from the Russian

by

NICHOLAS WEINSTEIN

MIR PUBLISHERS MOSCOW 1967

CONTENTS

Introduction (V. V. Danilevsky)	13
---	----

PART I

METAL-CUTTING PRINCIPLES, MACHINE TOOLS FOR METAL CUTTING, AND CUTTING TOOLS

<i>Chapter 1. Fundamentals of Metal Cutting (V. V. Danilevsky)</i>	17
1-1. Typical Forms of Surfaces on Machine Components and Relative Motions of the Work and Tool in Cutting Metals	17
1-2. Types of Cutting Processes	18
1-3. Elements of Single-Point Tools	18
1-4. Chief Elements in Metal Cutting	21
1-5. Process of Chip Formation	22
1-6. Properties of the Surface Layer Which Are Changed in Machining	23
1-7. Tool Life	25
1-8. Influence of Various Factors on the Cutting Speed	26
1-9. Tool Wear	27
1-10. Forces Acting on the Cutting Tool in Metal Cutting	28
1-11. Power Required in Metal Cutting	30
1-12. Metal-Cutting Tool Materials	30
1-13. Machining Time in Machining Operations	33
1-14. High-Velocity Metal Cutting and the Accomplishments of Progressive Machine Tool Operators	34
<i>Chapter 2. Principal Types of Metal-Cutting Machine Tools and Their Chief Mechanisms (V. V. Danilevsky)</i>	37
2-1. Machine Tool Classification According to Process Engineering Principles	37
2-2. Chief Types of Machine Tool Drives	38
2-3. Types of Transmission Used in Machine Tools	38
2-4. Speed-Changing Mechanisms for Main and Feed Drives of Machine Tool	42

2.5. Reversing Mechanisms	43
2.6. Main Requirements for Machine Tools Operating at High Cutting Speeds	44

Chapter 3. Types of Metal-Turning Machines and Their Applications
(D. P. Maslov and V. V. Danilevsky)

3-1. Classification of Metal-Turning Machines	45
3-2. Engine Lathes	45
3-3. Accessories for Metal-Turning Machines	45
3-4. Facing Lathes	53
3-5. Vertical Turret Lathes and Vertical Turning and Boring Mills	63
3-6. Turret Lathes	63
3-7. Single-Spindle Semiautomatic Multiple-Tool Lathes	66
3-8. Multiple-Spindle Semiautomatic Chucking Machines	67
3-9. Automatic Bar Machines	71
3-10. Safety Measures in Lathe Operation	75

Chapter 4. Drilling and Boring Machines and Their Applications
(D. P. Maslov and V. V. Danilevsky)

4-1. The Drilling Process	82
4-2. Elements of Metal Cutting and Forces Acting in Drilling	85
4-3. Boring and Reaming	87
4-4. Drilling Machines	90
4-5. Boring Machines	94
4-6. Tooling for Drilling and Boring Machines	96
4-7. Tool-Holding Devices for Drilling Machines	101
4-8. Determining Machining Time in Drilling	105
4-9. Safety Measures in Drilling Machine Operation	106

Chapter 5. Planers, Shapers and Slotters and Their Applications
(V. V. Danilevsky)

5-1. The Process of Planing Metals	107
5-2. Elements of Metal Cutting and Forces Acting in Planing	108
5-3. Power Required in Planing	108
5-4. The Slotting Process	109
5-5. Single-Point Planing and Slotting Tools	109
5-6. Planers and Shapers	111
5-7. Slotters	115
5-8. Operations Performed by Planers, Shapers, and Slotters	115
5-9. Determining Machining Time in Planing and Slotting	115
5-10. Safety Measures in Planer, Shaper, and Slotter Operation	118

